





[REDACTED] Plant




KODAK SAFETY FILM



[Redacted]  
Plant






ELECTRICAL ROOM

← Wiring destroyed  
(this depicts 1 of 3 boxes)


Electrical Fuse Box's Wiring

Destroyed ↓






Wiring pulled & cut from  
FUSE BOXES



Work Machines  
Destroyed



Hough 90E Series Loader  
(Guts torn out...)

WORK ROOM DESTRUCTION  
Industrial Tools Stolen  
(Slag Plant)



Plexiglass - after  
(continued)

